### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-001562 Address: 333 Burma Road **Date Inspected:** 15-Feb-2008

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1500 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Xu Le Feng, Ye Yong Jun **CWI Present:** Yes No **Inspected CWI report:** Yes No N/A **Rod Oven in Use:** Yes No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS: Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** Tower Mock-ups and OBG

# **Summary of Items Observed:**

The Quality Assurance (QA) Inspector Gregory Bertlesman arrived on site at the Zhenhua Port Machinery Company facility on Changxing island, China to periodically monitor welding and Quality Control functions. While on site the Quality Assurance Inspector observed and/or discovered the following.

## **Tower Fabrication Facility**

The Quality Assurance Inspector observed ZPMC performing fit-up operations to a corner stiffener within the 77M Mock-up.

The Quality Assurance Inspector observed no cutting of material taking place on the cutting table.

#### Bay 1

The Quality Assurance Inspector observed ZPMC squaring the length of closed ribs on the milling machine. Eight ribs were stacked and being milled simultaneously. The Quality Assurance Inspector measured the ribs to be approximately 8.5 meters in length, 12 millimeters in thickness and 790 millimeters in width. The Quality Assurance Inspector observed ZPMC drilling bolt holes in the closed ribs. ZPMC was observed beveling closed ribs in preparation for the partial joint penetration connection to the deck plate. ZPMC Quality Control would measure the bevel angle and record the values on the closed rib. The general appearance of the bevel appeared to be rough and contain sharp edges. After beveling, ZPMC was observed bending the closed ribs and performing dimensional inspections.

# Deck Panel Fit-up

The Quality Assurance Inspector observed ZPMC fitting up and tack welding of closed U ribs to deck plate

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

DP-015-001, utilizing the flux cored arc welding process to produce the tack welds in the horizontal position.

### Production Monitoring Test (PMT)

The Quality Assurance Inspector was present for production monitoring tests for Deck Panel DP-058-001. The Quality Assurance Inspector observed ZPMC Quality Control Inspector Sun Wei monitoring the welding. The welding parameters were recorded in an on site log for future review. After the gas metal arc welding root pass was complete ZPMC was observed grinding the tack weld areas in preparation for the submerged arc welding cover pass. There were various representatives from ZPMC/ABF and Caltrans present.

## Bay 2

114 M Tower Mock-Up Lower Shaft Assembly

The Quality Assurance Inspector observed ZPMC performing fit up operations of an exterior bolted connection plate at skin A.

The Quality Assurance Inspector observed ZPMC drilling 30 mm holes in various bolted interior stiffener connections.

## Bay 8

The Quality Assurance Inspector observed no ZPMC personnel working on the Caltrans project.

# **Summary of Conversations:**

As stated in the contents of the above report.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

<b>Inspected By:</b>	Bertlesman, Greg	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer